

RAJAS DENTAL COLLEGE & HOSPITAL

KAVALKINARU JN. - 627105.

MRL/REF/RDCH/ BME/PEDO/009

Date: 27/4/23

From

To

The Chairman, RDCH

Name : Dr. A. Esai Amutha Prabha

Designation : Reader

Dept. : Pedodontics & Preventive Dentistry

Repairs & Maintenance Work-Type

I report the following repair and maintenance work for your immediate action.

SL. No.	Nature of Work	Place of Work
1.	Chair No. 15 - Suction Stand loose	OP area
2.	Chair - 18 - Chair Stucking in up & down movements	OP area
Name and Signature Staff who submits the MRL: <i>Dr. A. Esai Amutha Prabha</i> Recommendation with estimated cost of the work (attach details) 1. Chair No: 15 Suction Stand loose rectified. 2. Chair No: 18 Stucking rectified.		Completion / Non Completion Report Work Completed the repair/ maintenance work as required in MRL on 03/05/23. It works smoothly. <i>[Signature]</i> PRINCIPAL RAJAS DENTAL COLLEGE & HOSPITAL KAVALKINARU JN - 627 105. TIRUNELVELI DISTRICT. <i>[Signature]</i> Staff <i>[Signature]</i> Co-ordinator

Technical Staff

Co-ordinator

Approved/Rejected with remarks

CFO/CAO

CHAIRMAN

RAJAS DENTAL COLLEGE & HOSPITAL

KAVALKINARU JN. - 627105.

MRL/REF/RDCH/ BME / PEDO / 011

Date: 6/6/23.

From

To

Name : Dr. A. Esai Amutha Prabha

The Chairman, RDCH

Designation : Reader.


Dept. : Pedodontics and Preventive Dentistry

Repairs & Maintenance Work-Type

I report the following repair and maintenance work for your immediate action.

SL. No.	Nature of Work	Place of Work
1.	Chair No 10, 11, 14, 19, 20 - Airrotor line not working	Op area
2	Chair no 14 - water leakage	Op area
3	Airrotor hand piece not work	Op area.
Name and Signature		Completion / Non Completion Report
Staff who submits the MRL	ASL 6/6/2023 Dr. A. Esai Amutha Prabha	
Recommendation with estimated cost of the work (attach details)		
1) Chair NO - 10, 11, 14 Foot Pedal wire cut. Rectified.		Work Completed the repair/ maintenance work as required in MRL on 7/6/23. It works smoothly.
2) Chair NO - 19. Three way syringe Air tube cut. Rectified.		
3) Chair NO - 20 Airrotor PCB Board loose connection. Rectified.		
4) Chair NO - 14 Tumble setting changed		
5) Airrotor hand piece, Para air rotator cartridge. Replaced		
Technical Staff	Co-ordinator	Staff
		Co-ordinator

Approved/Rejected with remarks



CHAIRMAN

RAJAS DENTAL COLLEGE & HOSPITAL

KAVALKINARU JN. - 627105.

MRL/REF/RDCH/

A/0037

Date: 14/09/23

From

To

Name : Dr. P. Faislin


The Chairman, RDCH

Designation : Senior Lecturer

Dept. : Periodontics


Repairs & Maintenance Work-Type

I report the following repair and maintenance work for your immediate action.

SL. No.	Nature of Work	Place of Work
1.	Autoclave → (1) (not working)	UL
2.	Scaler → (18), (15), (14), (11), (10) (not working)	UL
3.	Foot pedal → (14) (not working)	UL
4.	Suction → (7), (19) (not working)	
Name and Signature		Completion / Non Completion Report
Staff who submits the MRL	Dr. P. Faislin	
Recommendation with estimated cost of the work (attach details)		 Completed the repair/ maintenance work as required in MRL on . It works smoothly.
		
Technical Staff	Co-ordinator	Staff Co-ordinator

Approved/Rejected with remarks

CFO/CAO



CHAIRMAN